CARR-207 DR. JACOB J. WEAVER, SR. HOUSE

1812, rebuilt 1859

Union town

private

CARR-207 Dr. Jacob J. Weard, Sc. House

3406 Uniontown Road provides an interesting interpretation of the rural Victorian-style architecture in Uniontown. Development of Victorian architecture occurred during a period when there was tremendous growth in popular magazines, many of which ran articles or regular columns on architecture or household improvements. Remodeling to bring one's old house up to fashionable standards of ornamentation was a frequent subject of these articles. At 3406 Uniontown Road, Dr. Jacob J. Weaver. Sr., who practiced medicine in Uniontown from 1848 to 1880, used some of the standard mid-nineteenth century remodeling techniques to create an up-to-date dwelling. In 1859, he purchased this property with a log house that appears to have been built by David Stem in 1812. The property had been owned by Jacob Appler from 1814 to 1846. The three central bays of the house are the original log structure. Weaver did primarily two things in his Victorian-style remodeling. He added a gable-front wing with period ornamentation on the east side, and he covered the entire surface with a board-andbatten exterior. The wing has excellent examples of ornamentation including bracket cornices over the windows, a circular window in the gable, and scalloped bargeboard. Be sure to look closely at the beveled battens which have a refined touch in the way they end with arched curves instead of running squarely straight to the eaves. The one-story wing on the west side was the doctor's office for Dr. Weaver and his son.



COUNTY:

LOCATION:

TOWN:

## DEPARTMENT OF PLANNING AND DEVELOPMENT

225. N. Center Street Westminster, Maryland 21157

## WESTMINSTER PLANNING DISTRICT

FIELD SHEET--HISTORIC RESOURCES SURVEY

CARRCLL

FUNCTIONAL TYPE: ves. eluce

Unin town

3406 Unintown Rd

COMMON NAME: DR. JACCE J. WEAVER, SR HOUSE

	SUFVEY NUMBER: CARR 207	_	
T	NEGATIVE FILE NUMBER:		
	UTM REFERENCES: Zone/Easting/Northing		
Ž	U.S.G.S. QUAD. MAP: New Windsor	_	
	TRESENT FORMAL NAME:	_	
	ORIGINAL FORMAL NAME:	_	
	PRESENT USE: residence		
_	ARCHITECT/ENGINEER:		
4	BUILDER/CONTRACTOR:	4	
7	PHYSICAL CONDITION OF STRUCTURE:	$\dashv$	
	Excellent ( ) Good (X ) Fair ( ) Poor ( )		
	THEME: STYLE: yural Victorian	1	
DATE BUILT: 1912, remodeled 859			
in property 33			
( ) Concrete Block ( )			
oon ()			
( ) Concrete ( ) Concrete Block ( )			
ing ( ) Board and Batten (X) ) Novelty ( ) Stucco ( ) Sheet Metal ( ) e ( ) Brick Veneer ( ) Stone Veneer ( ) Other:			
oncrete ( )			
Asphalt Shingle ( ) Sheet Metal (<<) Le ( ) Other:			
Dormers () Chimneys () Sheds ()			
Mansard ( ) Gambrel ( ) Jerkinhead ( ) Bellcast ( ) With Parapet ( )			
Entrance Location: 2nd bay fun east			
LOCAL ATTITUDES:			
Positive (X) Negative ( ) Mixed ( ) Other:			

OWNER: The Control			
	PHYSICAL CONDITION OF STRUCTURE:		
3406 Uniontown Rd	Excellent ( ) Good (× )		
Lyrish team Ad 31187			
ACCESSIBILITY TO PUBLIC.			
11 AS ( )	THEME:		
LEVEL OF SIGNIFICANCE	STYLE: yural Victorian		
Local ( ) State ( ) National ( )	DATE BUILT:		
Local ( ) State ( ) National ( )  GENERAL DESCRIPTION:  Control of the state of the			
Structural System			
Foundations of			
1. Foundation: Stone (X) Brick () Concrete ( 2. Wall Structure	Congress Bl		
2. Wall Structure	( ) Concrete Block ( )		
A. Wood: Log (X) Post and Beam (X) Balloo  B. Wood Bearing Masonry: Brick (X)	- ()		
B. Wood Bearing Masonry: Brick () Stand			
B. Wood Bearing Masonry: Brick () Stone ( C. Iron () D. Steel () E. Other	Concrete ( ) Concrete Block ( )		
3. Wall Covering: Weatherboard ()			
3. Wall Covering: Weatherboard () German Siding () Board and Batten (X) Wood Shingle () Shiplap () Novelty () Stucco () Sheet Metal (			
Aluminum () Shiplap ()	Novelty ( ) Stucco ( ) Short W. T. ( )		
Radminum ( ) Asphalt Shingle	() Brick Veneer () Sheet Metal ()		
4. Roof Structure	Novelty () Stucco () Sheet Metal () () Brick Veneer () Stone Veneer ()		
Detactiff P	ULDOP!		
A. Truss: Wood (X) Iron () Steel () Concrete ()  B. Other:			
5. Pro-5.0			
J. ROOF Covering: Slate ( ) Wood Shingle ( )	Agmbata gran a		
5. Roof Covering: Slate () Wood Shingle () Asphalt Shingle () Sheet Metal (			
ing incerting Series income ( ) other.			
/· Utner:			
Appendages: Porches (x) Toward ()			
Appendages: Porches (X) Towers () Cupolas () Dormers () Chimneys () Sheds ()  Roof Style: Gable (X) Hip () Shed () Floring Dr. Office			
Roof Style: Gable (X) Hip () Shed () Flat () Saw Tooth () With Monitor () With B	Vies Office Sheds ()		
Saw Tooth () Shed () Flat ()	Mansard ( ) Gambrol ( )		
Saw Tooth () With Monitor () With B With False Front () Other:	ellcast () With Days ( )		
	with Parapet ( )		
Number of Bearing 1/2	,		
Number of Bays: 5 x 2	ntrance Location: 2" bay for east		
Approximate Dimensions:	ittrance Location: L bay the east		
	0		
<b>~</b>			
TUDEAT TO COMME			
THREAT TO STRUCTURE:	LOCAL ATTITUDES:		
	Positive AAA		
- Deterioration ( ) Deterioration	Positive (X) Negative ( )		
Alteration () Other:			
· · · · · · · · · · · · · · · · · · ·			





- 1. CARR-207 Dr. J. J. Weaver, Sr., House
- 2. Carroll County, Maryland
- 3. Joe Getty
- 4. November, 1984
- 5. Maryland Historical Trust, Annapolis, MD 6. South elevation (camera facing north)
- 7. 1/1